

~~C-O-N-F-I-D-E-N-T-I-A-L~~

SEE BOTTOM OF PAGE FOR SPECIAL CONTROLS, IF ANY

INFORMATION REPORT

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

PREPARED AND DISSEMINATED BY

CENTRAL INTELLIGENCE AGENCY

COUNTRY

China

SUBJECT

NAVY Review Completed

Port Information on Dairen

DATE DISTRIBUTED

25 Jul 58

25X1

NO. OF PAGES

4

NO. OF ENCLS.

SUPPLEMENT TO REPORT #

25X1

THIS IS UNEVALUATED INFORMATION

25X1

The Office of Naval Intelligence furnished the following information to CIA for IAC dissemination in accordance with paragraph 3c of NSCID #7.

25X1

25X1

1.

2.

3.

4.

5.

6.

7.

~~C-O-N-F-I-D-E-N-T-I-A-L~~

DISTRIBUTION	STATE	ARMY	NAVY	AIR															
--------------	-------	------	------	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NOFORN

NO DISSEM ABROAD

LIMITED

LIMITED: Dissemination limited to full-time employees of CIA, AEC and FBI; and, within State and Defense, to the intelligence components, other offices producing NIS elements, and higher echelons with their immediate supporting staffs. Not to be disseminated to consultants, external projects or reserve personnel on short term active duty (excepting individuals who are normally full-time employees of CIA, AEC, FBI, State or Defense) unless the written permission of the originating office has been obtained through the Assistant Director for Central Reference, CIA.

C-O-N-F-I-D-E-N-T-I-A-L

NAVY Review Completed

- 2 -

25X1

8.

25X1

9. Harbor regulations were posted. They were printed in three languages: Chinese, Russian and English.

10. Berths.

Piers were in good condition, of earth construction faced with stone, and with concrete slabs on top.

25X1

Buildings on the piers were of stone or brick construction, one story high, and roofed with corrugated metal. a concrete passageway for pedestrians was under construction over the railroad tracks at the inner end of Pier No 2. The gate for entrance to and exit from the port area was located at this point.

25X1

25X1

quite near the end of the tram line

25X1

11. only one fixed crane. This was located on Pier No 2, close to the northeast corner, in berth 14.

25X1

it was used to hoist a small fishing vessel of about 60 DWT to the deck of a Soviet freighter

25X1

There were numerous small mobile cranes on the piers. These were of about two tons capacity. Motive power was electricity, furnished by batteries. For lifts heavier than two tons, two cranes were used at a time. no mobile equipment powered by internal combustion engines, and petroleum products were in short supply. Electric-driven fork lifts were plentiful. A mobile conveyor belt was on Pier No 3.

25X1

25X1

25X1

12. Potable water of good quality was available on the piers.

Electricity was available on all piers,

25X1

coal bunkers furnished to one Chinese vessel. In this instance, coal was in canvas baskets which were placed on deck by crane and struck below by manpower. Railroad track appeared to be of standard gauge. Railroad cars were of about 25 tons capacity, and were equipped with couplings. Equipment was in good condition.

25X1

25X1

25X1

13.

14.

C-O-N-F-I-D-E-N-T-I-A-L


NOFORNNO DISSEM ABROADLIMITED

C-O-N-F-I-D-E-N-T-I-A-L

25X1

- 3 -

15. Shipping. [redacted] in Dairen, [redacted] numerous Chinese ships in port. All were timber carriers of about three thousand DWT, with two kingposts on the forecastle head and two on the poop, and had four hatches. All were coal burners. All loaded logs and pig iron, and one loaded bagged coke. [redacted] one Chinese ship carried the block from a large diesel engine as deck cargo. All the Chinese vessels were equipped with radars, [redacted]; "the same as those on Soviet Liberties." 25X1
16. In addition to the Chinese vessels, [redacted] the presence of Soviet, [redacted] ships. One Soviet freighter was [redacted] at Berth No 14, where she loaded a small fishing vessel of about 60 DWT. Another, [redacted] named "Kuibyshev" or something similar, was at Berth No 30, where she loaded bagged soy beans. [redacted] 25X1
17. Construction and Industry. [redacted] a small crane and about 30 triangular-shaped concrete blocks on the North Breakwater, opposite the end of Pier No 3. Blocks were shaped approximately as shown below: 25X1



- [redacted] Two industrial plants located to the north of Wharf No 2 in the Kanseishi District were in operation. [redacted] one might be an oil refinery. Another plant, also [redacted] an oil refinery, was located to the northeast of the Kanseishi East Breakwater. This plant also was in operation. [redacted] no other large industrial plants. 25X1
18. Shipbuilding and Repair. [redacted] at least six Soviet Liberties and two other Soviet vessels of five thousand DWT in the repair yards to the west of Pier No 4, and alongside Hamacho Pier. A new ship of from five- to six-thousand DWT was being built in one of the graving docks. About 12 small fishing vessels or patrol craft, similar to the one hoisted aboard the Soviet freighter, were being completed and outfitted. They were of about 60 DWT each. One Liberty ship was in drydock. Several Chinese junks were also in the yard, but [redacted] 25X1
19. Military Installations. [redacted] an old hulk [redacted] was moored to the end of Pier No 4, and apparently was in use as a Navy training craft. [redacted] it was used simply to house the Navy men. [redacted] 25X1

C-O-N-F-I-D-E-N-T-I-A-L

NOFORNNO DISSEM ABROADLIMITED

C-O-N-F-I-D-E-N-T-I-A-L

- 4 -

- [redacted] visual signals being exchanged between this craft and a signal station located at the end of the East Breakwater. [redacted] a few soldiers in town, [redacted] must be recruits, as they had difficulty keeping in step. Five jet aircraft passed over the harbor on one occasion, but [redacted] no airfield. No naval vessels [redacted]
20. General. All shipping agency problems were handled by the China Ocean Shipping Agency, a State-owned concern. The agent appeared to be a devoted Communist. [redacted]
21. [redacted] local officials appeared most sensitive to real or fancied slights to their country. They warned that any derogatory remarks would lead to severe punishment. They were very particular concerning display of the flag of the Chinese People's Republic. [redacted]
22. [redacted] the Seamen's Club, [redacted] was located on Yamagata Dori about five or six blocks from East Circle. Beer, liquor, and cigarettes were plentiful, of good quality, and quite cheap. Souvenirs, camphor chests, etc, could be had. The streets between the port area and the Seamen's Club were very clean. [redacted] only one passenger automobile and a very few trucks [redacted] in town. There were very few people on the streets. [redacted]
23. [redacted] a signal station at the southern tip of Daisanzan To.
24. [redacted]

- end -

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD

LIMITED